Oil Field Environmental Incident Summary

Responsible Party: Plains Marketing

Well Operator: ONEOK ROCKIES MIDSTREAM

Well Name: Stockyards Compressor Station

Field Name: Well File #:

Date Incident: 3/18/2016 Time Incident: 11:00 Facility ID Number:

County: WILLIAMS Twp: 154 Rng: 99 Sec: 7 Qtr:

Location Description: Stockyard Compressor Station

6 miles east of Williston on Hwy 1804 and 1 mile north on 129th Ave

48.175481854163785 103.47292914959124

Submitted By: Kim Rudningen Received By:

Contact Person: John Burnsfield

5990 Front St W Williston, ND 58801

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well: Type of Incident: Pump Leak

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil Brine

Other 3 Gallons

Description of Other Released Contaminant:

Natural Gas condensates

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

There were no immediate risks associated with this release

Areal Extent:

an area of about 4 X 6 feet was impacted, but was contained

Potential Environmental Impacts:

No environmental impacts are expected as this was cleaned up immediately.

Action Taken or Planned:

Plains immediately closed valves to stop the leak. The gravel and soil were immediately cleaned up and removed to pails for disposal. New gravel was brought back to replace that which was removed. The pump was repaired.

Wastes Disposal Location: Certified Landfill

Agencies Involved:

Updates

Date: 3/21/2016 Status: Reviewed - Assigned to Other Agency Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release remained on location. NDIC has oversight.

Date: 3/22/2016 Status: Inspection Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 9:30. Cloudy, SE wind 15-25 mph, 28 degrees F. Phoned the company representative to get specifics on the location of the release. According to the company representative, the release occurred next to the condensate tanks, near the getty box. Walked into the facility, took photos and observed the area described by the company contact. It appeared that the area described had new soil/scoria placed below the middle getty box. Due to the low volume of release and visual observation of new scoria placed in area described by company representative, no further follow-up will be needed at this time. However, as is common in these facilities, other small stains on facility surfaces were noted during inspection.